












Inch

# Headlamp Screws, etc. - Automotive

Pouces

# Vis de phares, etc. - Automobile

<p><b>Headlight Adjusting Screw and Nut</b> <b>599-001</b> Not serviced by OEM</p>  <p>Steel, Zinc Pltd. Screw Size 1/4"-28 x 1"</p> <p><b>American Motors Cars '69 - '71 with Dual Headlamps</b></p> <p><b>UNIT PACKAGE 25</b></p>	<p><b>Headlamp Adjusting Nut and Screw</b> <b>599-003</b> Not Serviced by OEM</p>  <p>Screw Size 12-28 x 1-1/2"</p> <p><b>Datsun, Toyota '69 - '72</b></p> <p>Steel, Zinc Pltd. Nylon</p> <p><b>UNIT PACKAGE 25</b></p>	<p><b>ZINC PLATED</b></p> <p><b>Headlight Adjusting Screw</b></p> <table border="1"> <thead> <tr> <th></th> <th></th> <th></th> <th>UNIT PACKAGE</th> </tr> </thead> <tbody> <tr> <td><b>2118-A</b></td> <td>1/4"-28 x 1"</td> <td><b>All Cars</b></td> <td>25</td> </tr> <tr> <td><b>2118-B</b></td> <td>1/4"-28 x 1-1/2"</td> <td><b>GM Cars (5956686)</b></td> <td>25</td> </tr> <tr> <td><b>B-1946</b></td> <td>1/4"-28 x 1-5/8"</td> <td><b>Ford Line (C6SZ-13032-A)</b></td> <td>50</td> </tr> </tbody> </table> <p>P.C. 599</p>				UNIT PACKAGE	<b>2118-A</b>	1/4"-28 x 1"	<b>All Cars</b>	25	<b>2118-B</b>	1/4"-28 x 1-1/2"	<b>GM Cars (5956686)</b>	25	<b>B-1946</b>	1/4"-28 x 1-5/8"	<b>Ford Line (C6SZ-13032-A)</b>	50
			UNIT PACKAGE															
<b>2118-A</b>	1/4"-28 x 1"	<b>All Cars</b>	25															
<b>2118-B</b>	1/4"-28 x 1-1/2"	<b>GM Cars (5956686)</b>	25															
<b>B-1946</b>	1/4"-28 x 1-5/8"	<b>Ford Line (C6SZ-13032-A)</b>	50															
<p><b>599-006</b> Screw Size 1/4"-28 x 1-1/2" (Replaces 1235816)</p>  <p>Steel, Zinc Pltd. Spring Steel Phosphate (Black) Nylon</p> <p><b>Headlamp Adjusting Screw and Nut</b> <b>Buick '69 - '73</b> <b>Cadillac '71 - '73</b> <b>Pontiac '68 - '69 All</b> <b>'70 - '72 Firebird, '73 All</b></p> <p><b>UNIT PACKAGE 10</b></p>	<p><b>599-008</b> (Replaces 3574084)</p>  <p>Screw Size 12-28 x 1-1/2"</p> <p>Steel Zinc Pltd. Nylon</p>	<p><b>599-024</b> (Replaces DOAZ-13032A)</p>  <p>Screw Size 1/4"-28 x 1"</p> <p>Steel, Zinc Pltd. Nylon</p> <p><b>Headlamp Adjusting Screw &amp; Nut Assembly</b> <b>G.M. Cars '62 - '64</b></p> <p><b>UNIT PACKAGE 25</b></p>																
<p><b>599-005</b> Headlamp Adjusting Screw. Steel, Plain Black Phosphate</p>  <p>Screw Size 1/4"-28 x 1"</p> <p><b>Ford Products with Disappearing Headlamps '69 - '71</b></p> <p><b>UNIT PACKAGE 50</b></p>	<p><b>Headlamp Adjusting Screw and Nut</b> <b>Chrysler Products '72 Monaco Only</b></p> <p><b>UNIT PACKAGE 25</b></p>	<p><b>C-643</b> Headlamp Screw Assembly (5948838) (with 2118-A Screw and mounting screws &amp; nuts)</p>  <p><b>G.M. Cars</b> Adjusting Screw Size 1/4"-28 x 1"</p> <p>Steel Zinc Pltd. White Plastic</p> <p><b>UNIT PKG. 5 Sets</b></p> <p>P.C. 086</p>																
<p><b>599-002</b> Headlight Adjusting Screw and Nut</p>  <p>Steel, Zinc Pltd. Nylon</p> <p>Screw Size 1/4"-28 x 1"</p> <p>Not Serviced by OEM</p> <p><b>American Motors Cars '69 - '71 with Single Headlight</b></p> <p><b>UNIT PACKAGE 25</b></p>	<p><b>ST-2010P</b> Parking and Tail Lamp Screws Stainless Steel - Type "F" Screw Size 8-32 x 1-3/8"</p>  <p><b>Used on Ford '56 - '60 (Mfrs. No. 372678-S100)</b></p> <p><b>UNIT PACKAGE 50</b></p> <p>P.C. 531</p>	<p><b>599-014</b> (Replaces 3573797)</p>  <p>Screw Size 12-28 x 1-1/2"</p> <p><b>Headlight Beam Adjusting Screw and Nut Assembly</b> <b>Chrysler Products '71</b></p> <p><b>UNIT PACKAGE 25</b></p>																
	<p><b>599-011</b> Headlamp Adjusting Screw and Stop</p>  <p>Screw Size 1/4"-28 x 1-1/2"</p> <p>Black Nylon</p> <p><b>Chrysler Cricket 1972</b></p> <p><b>UNIT PACKAGE 25</b></p>																	

H

CATALOG 13