

	$\frac{1}{64}$.015625		$\frac{33}{64}$.515625
	$\frac{1}{32}$.03125		$\frac{17}{32}$.53125
	$\frac{3}{64}$.046875		$\frac{35}{64}$.546875
$\frac{1}{16}$.0625	$\frac{9}{16}$.5625
	$\frac{5}{64}$.078125		$\frac{37}{64}$.578125
	$\frac{3}{32}$.09375		$\frac{19}{32}$.59375
	$\frac{7}{64}$.109375		$\frac{39}{64}$.609375
$\frac{1}{8}$.125	$\frac{5}{8}$.625
	$\frac{9}{64}$.140625		$\frac{41}{64}$.640625
	$\frac{5}{32}$.15625		$\frac{21}{32}$.65625
	$\frac{11}{64}$.171875		$\frac{43}{64}$.671875
$\frac{3}{16}$.1875	$\frac{11}{16}$.6875
	$\frac{13}{64}$.203125		$\frac{45}{64}$.703125
	$\frac{7}{32}$.21875		$\frac{23}{32}$.71875
	$\frac{15}{64}$.234375		$\frac{47}{64}$.734375
$\frac{1}{4}$.25	$\frac{3}{4}$.75
	$\frac{17}{64}$.265625		$\frac{49}{64}$.765625
	$\frac{9}{32}$.28125		$\frac{25}{32}$.78125
	$\frac{19}{64}$.296875		$\frac{51}{64}$.796875
$\frac{5}{16}$.3125	$\frac{13}{16}$.8125
	$\frac{21}{64}$.328125		$\frac{53}{64}$.828125
	$\frac{11}{32}$.34375		$\frac{27}{32}$.84375
	$\frac{23}{64}$.359375		$\frac{55}{64}$.859375
$\frac{3}{8}$.375	$\frac{7}{8}$.875
	$\frac{25}{64}$.390625		$\frac{57}{64}$.890625
	$\frac{13}{32}$.40625		$\frac{29}{32}$.90625
	$\frac{27}{64}$.421875		$\frac{59}{64}$.921875
$\frac{7}{16}$.4375	$\frac{15}{16}$.9375
	$\frac{29}{64}$.453125		$\frac{61}{64}$.953125
	$\frac{15}{32}$.46875		$\frac{31}{32}$.96875
	$\frac{31}{64}$.484375		$\frac{63}{64}$.984375
$\frac{1}{2}$.5	1		.

CATALOG 13

R